

Inspection Photos

API: 005-06417

Operator: JFH DISPOSAL LLC

Inspection Date: 12/2/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 005-06417 | Date: 12/2/2021

Inspection Photos



Photo 1. Facing northeast along the access road toward the well site. The electric utility at the location is in disrepair shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 005-06417 | Date: 12/2/2021

Inspection Photos



Photo 2. Facing southwest toward the well and tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 005-06417 | Date: 12/2/2021

Inspection Photos




Photo 3. Facing toward the well. Well sign installed at the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 005-06417 | Date: 12/2/2021