

Inspection Photos

API: 071-09210

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/8/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09210 | Date: 12/8/2021

Inspection Photos



Photo 1. Facing northwest toward the access road which has not been recontoured. The gate remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09210 | Date: 12/8/2021

Inspection Photos



Photo 2. Facing north toward the location. The location has not been recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09210 | Date: 12/8/2021

Inspection Photos



Photo 3. Facing south toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09210 | Date: 12/8/2021

Inspection Photos



Photo 4. North side of the location facing southwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09210 | Date: 12/8/2021

Inspection Photos



Photo 5. Drone aerial photo facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09210 | Date: 12/8/2021