

Inspection Photos

Operator: Arkoma Operations
API: 067-08478
Date: 12/7/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and sand dropseed.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of Russian knapweeds along the access road. Approx. 200 individuals observed.



Photo 5. View of reference area comprised of pinyon and juniper woodland with gambel oak, mountain mahogany, Indian ricegrass, and threadleaf sunflower.