

Inspection Photos
Operator: Simcoe
API: 067-09032
Date: 12/7/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of eastern project area from the southeastern corner facing northward. Revegetation is progressing here with crested wheatgrass, intermediate wheatgrass, sand dropseed, rubber rabbitbrush, and western wheatgrass.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of sagebrush shrubland with Indian ricegrass, James galleta, snakeweed, and prickly pear.