

# Inspection Photos

12/07/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 311604

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 311604



**Photo 1:** Photos taken from the production areas of the Location. Photos provide examples showing that control measures to stabilize the production areas, and to mitigate tracking and offsite sediment transport remain missing or insufficient.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 311604



**Photo 2:** Photos taken from the production areas of the Location. Photos provide examples showing that control measures to stabilize the production areas, and to mitigate tracking and offsite sediment transport remain missing or insufficient.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 311604



**Photo 3:** Photos taken from the production areas of the Location. Photos provide examples showing that control measures to stabilize the production areas, and to mitigate tracking and offsite sediment transport remain missing or insufficient.