

Inspection Photos

12/07/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323866

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 323866



Photo 1: Photo shows Operator has constructed a shallow sediment trap at the end of the ditch; outlet missing geotextile lining beneath the rip-rap material per good engineering practices.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 323866



Photo 2: Photo shows Operator has constructed a shallow sediment trap at the end of the ditch; outlet missing geotextile lining beneath the rip-rap material per good engineering practices.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 323866



Photo 3: Photo shows controls measures (netting) has been implemented at the containment BMP to prevent wildlife .

