

Batch ID: 78034 Document Name: Isotech File Name: 2019_11_18_Schnurr 65779-F Isotech NG4
COGCC.xls

SampleType: _____ Matrix: _____

Facility ID: 753870 Sample ID: 613645 Sample Name: Schnurr 65779-F Sample Date: 11/18/2019

Collection Point: Dom Matrix: WATER Pre Post: Voluntary Post drill

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 742464

Batch ID: 78032 Document Name: Trip Blank File Name: 2019_11_18_Schnurr 65779-F Trip Blank SGS
COGCC.xls

SampleType: _____ Matrix: _____

Facility ID: 753870 Sample ID: 613642 Sample Name: Schnurr 65779-F Sample Date: 11/18/2019

Collection Point: Dom Matrix: WATER Pre Post: Trip Blank

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA22062-1

Sample Facility Attachment:

No Facility Attachment

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

User Group	Comment	Comment Date
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	03/10/2020
Total: 1 comment(s)		