


**Inspection Photos**  
**Location Name: Harper Hill 1-29, 2-29**  
**Location ID: 423735**



**Photo 1. Overview of location taken facing northwest.**



**Photo 2. Stained soil around wellhead.**



**Inspection Photos**  
**Location Name: Harper Hill 1-29, 2-29**  
**Location ID: 423735**



**Photo 3. Stained soil on location.**



**Photo 4. Stained soil on location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources