

Inspection Photos
Location Name: Carpenter 2-32
Location ID: 312776



Photo 1. Overview of location taken facing east.



Photo 2. Access road overgrown.

