

**Inspection Photos**  
**Location Name: Schieck 11-31**  
**Location ID: 312984**



**Photo 1. Overview of location taken facing south. Dried annual weeds have become debris.**



**Photo 2. No bradenhead access apparent.**



**Inspection Photos**  
**Location Name: Schieck 11-31**  
**Location ID: 312984**



**Photo 3. Gauge hatch open.**



**Photo 4. Animal burrows in berm.**

