

Inspection Photos
Location Name: Dowdell 1
Location ID: 324668



Photo 1. Overview of location taken facing west.



Inspection Photos
Location Name: Dowdell 1
Location ID: 324668



Photo 2. No bradenhead access apparent.



Photo 3. Apparent spill down side of right tank.

