

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW

Location ID: 323833



Photo #5365 from entrance to location.



Photo #5366 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW

Location ID: 323833



Photo #5367 Storage tank not labeled.



Photo #5368 Sight glass indicates the storage tank is full of an unknown fluid.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW

Location ID: 323833



Photo #5369 Storage tank located under horizontal separator.