

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /33NESW

Location ID: 335316



Network:Dec 9, 2021 at 9:55:05 AM MST
Local:Dec 9, 2021 at 9:55:05 AM MST
+39.479204,-108.00714



Network:Dec 9, 2021 at 9:55:08 AM MST
Local:Dec 9, 2021 at 9:55:08 AM MST
+39.479204,-108.00714

Photo #5370 from entrance to location.

Photo #5371 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /33NESW

Location ID: 335316



Photo #5373 Storage tanks no labeled.



Photo #5374 Sight glass indicates the storage tank is full of an unknown fluid.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /33NESW

Location ID: 335316



Photo #5375 Storage tank located under Horizontal separator.