

Inspection Photos

12/07/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 439173

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 439173



Photo 1: Photo shows containment BMPs at tanks has not been maintained in proper functioning condition.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 439173



Photo 2: Photos examples showing control measures to protect and stabilize the cut slopes of the Location remain missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 439173



Photo 3: Photo taken from the east end of the Location. Photo shows Operator has placed/stored trash/rubbish on the ground adjacent to a full trash receptacle.

