

Inspection Photos

12/07/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 414294

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 414294



Photo 1: Photos examples showing control measures to stabilize the production area, mitigate tracking, degradation and sediment transport remains inadequate on the Location. .

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 414294



Photo 2: Photos examples showing control measures to stabilize the production area, mitigate tracking, degradation and sediment transport remains inadequate on the Location.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 414294



December 7, 2021
39.45510853N 107.80579513W

Photo 3: Photos examples showing control measures to stabilize the production area, mitigate tracking, degradation and sediment transport remains inadequate on the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 414294



Photo 4: Unused equipment removed from east end of the Location.

