

Inspection Photos

API: 071-08762

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/9/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08762 | Date: 12/9/2021

Inspection Photos



Photo 1. Facing north along the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08762 | Date: 12/9/2021

Inspection Photos



Photo 2. Facing north at the location. The access road continues thru the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08762 | Date: 12/9/2021

Inspection Photos



Photo 3. There are numerous undesirable weeds (Cocklebur) throughout the location. Seed heads should be removed to prevent dispersal.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08762 | Date: 12/9/2021

Inspection Photos



Photo 4. Facing toward the west slope of the location. There are signs of erosion and vegetation has not established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08762 | Date: 12/9/2021

Inspection Photos



Photo 5. Facing southwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08762 | Date: 12/9/2021

Inspection Photos



Photo 6. Northeast side of the location facing southwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08762 | Date: 12/9/2021