

Inspection Photos
Location Name: Antelope 14-20 PAD
Location ID: 423766




Photo 1 – 14-20 Wellhead – Unmarked Risers

Photo 2 – 13-20 Wellhead – Unmarked Risers

Inspection Photos
Location Name: Antelope 14-20 PAD
Location ID: 423766



Photo 3 – Separators



Photo 4 – Tank Battery

Inspection Photos
Location Name: Antelope 14-20 PAD
Location ID: 423766



Photo 5 – Tank Battery Signs