

**Inspection Photos**  
**Location Name: Antelope P-29 PAD**  
**Location ID: 428984**



**Photo 1 – Wellheads**



**Photo 2 – Wellheads**

**Inspection Photos**  
**Location Name: Antelope P-29 PAD**  
**Location ID: 428984**



**Photo 3 – Second Wellhead from the West missing Wellhead Sign**

**Photo 4 – Second Wellhead from the West missing Wellhead Sign**

**Inspection Photos**  
**Location Name: Antelope P-29 PAD**  
**Location ID: 428984**



**Photo 5 – Maintenance Tank**



**Photo 6 – Gas Meter Shed**

**Inspection Photos**  
**Location Name: Antelope P-29 PAD**  
**Location ID: 428984**



**Photo 7 – Separators**



**Photo 8 – Unmarked Risers in SW Corner**

**Inspection Photos**  
**Location Name: Antelope P-29 PAD**  
**Location ID: 428984**



**Photo 9 – Unmarked Riser**



**Photo 10 – Tank Battery**

Inspection Photos  
Location Name: Antelope P-29 PAD  
Location ID: 428984



Photo 11 – ECDs

Photo 12 – Location Signs at Entrance