

Inspection Photos
Location Name: Antelope F-32 PAD
Location ID: 432686



Photo 1 – Tank Battery Sign

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Antelope F-32 PAD
Location ID: 432686



Photo 3 – Wellheads




Photo 4 – Compressor – Stained Soil

Inspection Photos
Location Name: Antelope F-32 PAD
Location ID: 432686



Photo 5 – Unmarked Risers

Photo 6 – Unmarked Riser

Inspection Photos
Location Name: Antelope F-32 PAD
Location ID: 432686



Photo 7 – Separators and ECDs



Photo 8 – Tank Battery