

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/14/2021

Submitted Date:

12/14/2021

Document Number:

701600567

FIELD INSPECTION FORM
 Loc ID 312251 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10017

Name of Operator: CHACO ENERGY COMPANY

Address: P O BOX 1587

City: DENVER State: CO Zip: 80201

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Nelson, Matt	303-981-3840	matt@chacoenergy.com	Inspections/Ops. Engineer
Quint, Craig		craig.quint@state.co.us	
Wolfe, Stephen		stephen.wolfe@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219871	WELL	SI	05/15/2013	OW	075-07535	WRITEBOL 1	SI

General Comment:

MIT performed to remain in SI/TA status. MIT FAILED - WO concluded.

NOTE TO OPERATOR: Perform CA's within (6) months as of date of this FIR. Contact COGCC Engineering for directives.
Well must remain in SI/TA status until otherwise approved by COGCC Engineering.

Inspected FacilitiesFacility ID: 219871 Type: WELL API Number: 075-07535 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Failed MITCorrective Action: Repair of Plug well within designated CA date. Well must remain SI until approval to produce or plug well is attained from COGCC. Contact COGCC Engineering for directives.Date: 06/14/2022**Workover**Comment: MIT performed - Test failed, well did not hold pressure.Corrective Action: Repair with successful MIT performed/approved by COGCC within (6) months from the date of this FIR or submit to COGCC a Form 6 requesting plugging orders from COGCC Engineering. P&A must also be performed within the designated (6) month CA date. Contact COGCC Engineering for directives.Date: 06/14/2022**COGCC Comments**

Comment	User	Date
MIT performed - MIT FAILURE - Well must remain in SI/TA status until repairs and successful MIT are performed or well is PA within the designated (6) month CA date. Contact COGCC Engineering for directives.	schureky	12/14/2021