

Inspection Photos
Location Name: Duncan B-14
Location ID: 313205



Photo 1. Roads not maintained for winter.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources