

TEP
DOE 1-M-19
Location # 311545



location



location

TEP
DOE 1-M-19
Location # 311545



location



location

TEP
DOE 1-M-19
Location # 311545



Missing information



Lack of bull plugs/caps

TEP
DOE 1-M-19
Location # 311545



Lack of bull plugs/caps




Lack of bull plugs/caps

TEP
DOE 1-M-19
Location # 311545



Debris



Sight glass on storage tank

TEP
DOE 1-M-19
Location # 311545



Lack of stabilization/compaction



Lack of stabilization/compaction

TEP
DOE 1-M-19
Location # 311545



Lack of stabilization/compaction

