

Inspection Photos  
Operator: Simcoe  
API: 007-06123  
Date: 12/13/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Dense kochia debris up to 4ft tall needs to be removed.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of reference area comprised irrigated grass field. Vegetation is largely dormant and mowed at this time.