

**Inspection Photos**  
**Location Name: State Antelope F-30 PAD**  
**Location ID: 432809**



**Photo 1 – Wellheads – Unused Lubricator body**




**Photo 2 – Compressor**

**Inspection Photos**  
**Location Name: State Antelope F-30 PAD**  
**Location ID: 432809**



**Photo 3 – Compressor – Unmarked Riser**



**Photo 4 – Compressor – Unmarked Risers and Stained Soil**



**Inspection Photos**  
**Location Name: State Antelope F-30 PAD**  
**Location ID: 432809**



**Photo 5 – Separators and ECD**



**Photo 6 – Tank Battery**

