

Inspection Photos
Location Name: Antelope J-19 PAD
Location ID: 430139



Photo 1 – Signs at Entrance



Photo 2 – Tank Battery



Inspection Photos
Location Name: Antelope J-19 PAD
Location ID: 430139




Photo 3 – South Tanks – NFPA Labels



Photo 4 – ECDs

Inspection Photos
Location Name: Antelope J-19 PAD
Location ID: 430139



Photo 5 – Compressor



Photo 6 – Day Tank – Netting Inadequate



Inspection Photos
Location Name: Antelope J-19 PAD
Location ID: 430139



Photo 7 – Compressor – Stained Soil



Photo 8 – Separators

Inspection Photos
Location Name: Antelope J-19 PAD
Location ID: 430139



Photo 9 – Unmarked 1" Risers



Photo 10 – Wellheads

