

Inspection Photos
Location Name: MDM 33-14
Location ID: 331806



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: MDM 33-14
Location ID: 331806



Photo 3 Access rd. to well

Photo 4 Access rd. to well

Inspection Photos
Location Name: MDM 33-14
Location ID: 331806



Photo 5 Access rd. to well

Photo 6 well site

Inspection Photos
Location Name: MDM 33-14
Location ID: 331806




Photo 7 Access rd. leading away from well

Photo 8 TB

Inspection Photos
Location Name: MDM 33-14
Location ID: 331806



Colorado Oil & Gas Conservation Commission
 4643 County Rd 20, Longmont, CO 80504, USA
 40.13463, -104.96779, 4799.8ft, 245°
 12/14/2021 11:19:26



Station Number	45403
Station Name	MDM 33, 34 -14
Static Range	500
Calibrated Static Span	500
Differential Range	250
Calibrated Diff. Span	250
Temperature Range	150
Meter Run Size	2.067

Legals		
Date	Orifice Size	Test Date
8-28-17	1.500	9-22-17
2-13-18	1.500	2-13-18
8-16-18	1.500	8-16-18
	1.875	8-24-20
	1.375	10-11-21

Colorado Oil & Gas Conservation Commission
 4643 County Rd 20, Longmont, CO 80504, USA
 40.13467, -104.96779, 4828.1ft, 320°
 12/14/2021 11:20:07

Photo 9 Gas Meter Run

Photo 10 card indicates current calibration