

Inspection Photos

API: 043-06170

Operator: JAVERNICK OIL

Inspection Date: 12/14/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06170 | Date: 12/14/2021

Inspection Photos



Photo 1. Facing east along the access road. The road has been graded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06170 | Date: 12/14/2021

Inspection Photos



Photo 2. Facing toward the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06170 | Date: 12/14/2021

Inspection Photos



Photo 3. Facing toward the pumpjack. The weeds have been removed from the pumpjack area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06170 | Date: 12/14/2021