

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2021

Submitted Date:

12/15/2021

Document Number:

699602468**FIELD INSPECTION FORM**Loc ID 430083 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**19 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430080	WELL	PR	08/01/2020	OW	123-36040	Wells Ranch State USX AA16-65-1HNL	PR
430084	WELL	PR	08/01/2020	OW	123-36043	Wells Ranch State USX AA16-64-1HNL	PR

**General Comment:**

This is a WELL inspection.  
Well(s): 2: Producing | PR.  
Battery: Active.

Centralized Battery serves 1 Tank Battery Facility ID  
(480961).  
Centralized Battery serves 6 Location IDs  
(430079, 428799, 428993, 430083, 430389, 430518).  
(Well(s): 15: Producing | PR; 1: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #699602459 and/or Facility ID #480961  
for Battery / Facility, Equipment info.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	CONTAINERS			
Comment:	Corrosion Inhibitor, Methanol.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #699602459 and/or Facility ID #480961 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	2: Wellsites.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	2: Wellsites. Iron panel.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Gas lift manifold. Iron panel.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #699602459 and/or Facility ID #480961 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Other	# 2			corrective date
Comment:	2: Wellsites. Gas lift injection lines.			
Corrective Action:				Date:

Type:	#	
Comment:	Refer to Field Inspection Report doc. #699602459 and/or Facility ID #480961 for Battery / Facility, Equipment info.	
Corrective Action:		Date:
Type: Plunger Lift	# 2	
Comment:	2: Wellsites.	
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	2: Wellsites. Appears plumbed to surface.	
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:	2: Gas lift allocation meters. Calibration cards indicate calibration within last year. Last calibration: 07/28/2021. Active.	
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	1: Corrosion Inhibitor pump, tank w/ drip containment. Placards. 1: Methanol pump, tank w/ drip containment. Placards.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.487004,-104.411922
Comment:	Centralized Battery serves 1 Tank Battery Facility ID (480961). Centralized Battery serves 6 Location IDs (430079, 428799, 428993, 430083, 430389, 430518).  Refer to Field Inspection Report doc. #699602459 and/or Facility ID #480961 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 430080 Type: WELL API Number: 123-36040 Status: PR Insp. Status: PR**Producing Well**Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 03/29/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 430084 Type: WELL API Number: 123-36043 Status: PR Insp. Status: PR**Producing Well**Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 03/22/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On TUE 12/07/2021 at approximately 15:52 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: Wells Ranch State USX /AA16-64-1HNL Pd  Location ID: 430083  Well Name(s):  Wells Ranch State USX AA16-65-1HNL, Wells Ranch State USX AA16-64-1HNL.  API: 05-123-36040, 05-123-36043.  Location County: Weld County, Colorado  Weather: Mostly Sunny, dry.</p> <p>While there, I observed:  Well(s): 2: Producing   PR.  Battery: Active.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (480961).  Centralized Battery serves 6 Location IDs (430079, 428799, 428993, 430083, 430389, 430518).  (Well(s): 15: Producing   PR; 1: Temporarily Abandoned   TA).</p> <p>Refer to Field Inspection Report doc. #699602459 and/or Facility ID #480961 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/15/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602469	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5608659">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5608659</a>