

Inspection Photos

Location Name: April 12-14 and Dryer 1 Tank Battery

Location ID: 317498



Photo 1 Tank Battery Sign

Inspection Photos
Location Name: April 12-14 and Dryer 1 Tank Battery
Location ID: 317498



Photo 2: Crude Oil and Produced Water AST



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: April 12-14 and Dryer 1 Tank Battery

Location ID: 317498



Photo 3 Example of gap in Pit #1 netting



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: April 12-14 and Dryer 1 Tank Battery
Location ID: 317498



COGCC
40.57721, -104.06707, 4823.6ft
12/08/2021 11:20:39

Photo 4 Pit 2 from east side looking west.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: April 12-14 and Dryer 1 Tank Battery
Location ID: 317498



COGCC
40.57716, -104.06712, 4822.2ft
12/08/2021 11:20:48

Photo 5 Pit 2 in foreground, looking west at Pits 3 & 4



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: April 12-14 and Dryer 1 Tank Battery
Location ID: 317498



Photo 6 Pits 3 & 4 looking west



Inspection Photos
Location Name: April 12-14 and Dryer 1 Tank Battery
Location ID: 317498




Photo 7 Pit 4 looking north west



Inspection Photos
Location Name: April 12-14 and Dryer 1 Tank Battery
Location ID: 317498



Photo 8 At southwest corner of Pit 4 looking east at pit complex



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources