

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSW

Location ID: 334971



Photo #5393 from entrance to location.



Photo #5394 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSW

Location ID: 334971



Photo #5395 Storage tank not labeled.



Photo #5396 Sight glass indicates the storage tank is full of an unknown fluid.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSW

Location ID: 334971



**Photo #5397 Storage tank located under horizontal separator.**