

# Final Reclamation Inspection

November 10th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 328048

Inspection Document #: 701900254

Weld County, CO

NENE Section 7 T3N R64W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Dechant 7-11  
Location ID: 328048



**Photo 1.** 2020 aerial imagery of the well pad (north is up). The tank battery (highlighted in blue) remains for the TA well 123-15477 not pictured to the south.

Inspection Photos  
Location Name: Dechant 7-11  
Location ID: 328048



**Photo 2.** Overview photo of the reclaimed well taken at ground level from west of the well facing east. Note: little to no vegetation established on reclaimed well or surrounding areas. Will need to re-inspect when vegetation has established.