

Final Reclamation Inspection

November 16th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323020

Inspection Document #: 701900262

SWNW Section 21 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Schneider 1
Location ID: 323020




Photo 1. 2021 aerial imagery of the well pad (north is up). The tank battery highlighted in blue has an open remediation (Doc # 401568468) and will need to be re-inspected when remediation closes.

Inspection Photos
Location Name: Schneider 1
Location ID: 323020



Photo 2. Overview photo of the reclaimed well pad taken at ground level from the eastern edge looking west. Note: well pad now resides in an industrial storage area.

Inspection Photos
Location Name: Schneider 1
Location ID: 323020



Photo 3. Overview photo of the tank battery taken at ground level from the northern edge looking south. Note: weedy annual vegetation dominates tank battery and gravel remains on site.

Inspection Photos
Location Name: Schneider 1
Location ID: 323020



Photo 4. Monitoring wells remain on site for the open remediation, doc # 401568468.