

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SESW

Location ID: 334749



Photo #5398 from entrance to location.



Photo #5399 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SESW

Location ID: 334749



Photo #5400 Storage tank not labeled.



Photo #5401 Sight glass indicates the storage tank is full of an unknown fluid.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SESW

Location ID: 334749



Photo #5402 Storage tank located under the horizontal separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources