

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 1 Location Sign at tank battery



Photo 2 Approximate former buried concrete vessel location



Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 3 Gearbox leaking onto ground



Photo 4 Gearbox leaks



Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 4 Exhaust area with fresh road base



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources