

**Inspection Photos**  
**Location Name: Morgan A #1**  
**Spill ID: 481051**



**Photo 1 – Excavation. Fencing down**



**Photo 2 – Excavation. Fencing down. Silt fence damaged by wind.**



**Inspection Photos**  
**Location Name: Morgan A #1**  
**Spill ID: 481051**



**Photo 3 – Excavation. Fencing down**



**Photo 4 – Silt fence damaged by wind.**