

Inspection Photos  
Location Name: Bangart 42-19  
Location ID: 317922



Photo 1 WH sign

Photo 2 WH

**Inspection Photos**  
**Location Name: Bangart 42-19**  
**Location ID: 317922**



**Photo 3 Pump Jack**

**Photo 4 ancillary equipment**

Inspection Photos  
Location Name: Bangart 42-19  
Location ID: 317922



Photo 5 TB sign

Photo 6 TB

Inspection Photos  
Location Name: Bangart 42-19  
Location ID: 317922



Photo 7 Horiz. Heated Sep.

Photo 8 Gas Meter Run