

Final Reclamation Inspection

December 14, 2021

Operator: VERDAD RESOURCES LLC #10651

Location ID: 457136

Inspection Document #: 697503570

Weld County, CO

NWSE Section 14 T9N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Rohn 9-60 /14A
Location ID: 457136



Photo 1. Photo taken from the location, facing East. Photo illustrates only two wells have been drilled at location.

