

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2021

Submitted Date:

12/17/2021

Document Number:

699602478

FIELD INSPECTION FORM

Loc ID 444924 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Medina, Justin		justin.medina@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444923	WELL	PR	11/01/2020	OW	123-42812	Lapp A15-613	PR

General Comment:

This is a WELL inspection.
Well(s): 1: Producing | PR.
Battery: Active.

Centralized Battery serves 1 Tank Battery Facility ID
(481166).
Centralized Battery serves 3 Location IDs
(419303, 444924, 444930).
(Well(s): 11: Producing | PR).

Refer to Field Inspection Report doc. #699602474 and/or Facility ID #481166
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #699602474 and/or Facility ID #481166 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:	Refer to Field Inspection Report doc. #699602474 and/or Facility ID #481166 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type:	#		
Comment:	Refer to Field Inspection Report doc. #699602474 and/or Facility ID #481166 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		

Corrective Action:					Date:	
<u>Tanks and Berms:</u>						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.485733,-104.504524	
Comment:		Centralized Battery serves 1 Tank Battery Facility ID (481166). Centralized Battery serves 3 Location IDs (419303, 444924, 444930). Refer to Field Inspection Report doc. #699602474 and/or Facility ID #481166 for Battery / Facility, Equipment info.				
Corrective Action:					Date:	
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 444923 Type: WELL API Number: 123-42812 Status: PR Insp. Status: PR**Producing Well**Comment: Producing | PR.

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 06/04/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: VAPOREnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 12/16/2021 at approximately 14:15 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: Lapp /A15-632 Pad Location ID: 444924 Well Name(s): Lapp A15-613. API: 05-123-42812. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481166). Centralized Battery serves 3 Location IDs (419303, 444924, 444930). (Well(s): 11: Producing PR).</p> <p>Refer to Field Inspection Report doc. #699602474 and/or Facility ID #481166 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/17/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602479	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5611022