

Inspection Photos

API: 071-09111

Operator: OGRIS OPERATING LLC

Inspection Date: 12/16/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09111 | Date: 12/16/2021

Inspection Photos



Photo 1. Facing southeast along the main access road. The access road has been regraded and sediment was cleaned out the cattle guard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09111 | Date: 12/16/2021

Inspection Photos



Photo 2. The culverts have been cleaned out and areas of erosion were repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09111 | Date: 12/16/2021

Inspection Photos



Photo 3. Facing toward the well. The water leak at wellhead was repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09111 | Date: 12/16/2021