

Inspection Photos

API: 071-09140

Operator: OGRIS OPERATING LLC

Inspection Date: 12/16/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09140 | Date: 12/16/2021

Inspection Photos



Photo 1. Facing northwest along the main access road. There are rock check dams installed along the side of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09140 | Date: 12/16/2021

Inspection Photos



Photo 2. Facing west along access road. The culverts along the road have been cleaned out and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09140 | Date: 12/16/2021

Inspection Photos



Photo 3. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09140 | Date: 12/16/2021