

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402898220

Date Received:

12/17/2021

Spill report taken by:

GINTAUTAS, PETER

Spill/Release Point ID:

481275

## SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

### OPERATOR INFORMATION

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Operator No: 47120	<b>Phone Numbers</b>
Address: P O BOX 173779		Phone: (970) 515-1698
City: DENVER State: CO Zip: 80217-3779		Mobile: ( )
Contact Person: Gregory Hamilton		Email: Gregory.Hamilton@ox.com

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402898220

Initial Report Date: 12/14/2021 Date of Discovery: 12/14/2021 Spill Type: Historical Release

#### Spill/Release Point Location:

QTRQTR SESW SEC 31 TWP 3N RNG 66W MERIDIAN 6

Latitude: 40.174474 Longitude: -104.823631

Municipality (if within municipal boundaries): County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

#### Reference Location:

Facility Type: TANK BATTERY

☒ Facility/Location ID No 480210Spill/Release Point Name: Vonderlage 22, 13, 39, 40  
-36 O SA☐ Well API No. (Only if the reference facility is well) 05- -☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): Unknown

Estimated Condensate Spill Volume(bbl): Unknown

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&amp;P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Has the subject Spill/Release been controlled at the time of reporting? Yes

#### Land Use:

Current Land Use: CROP LAND

Other(Specify):

Weather Condition: Sunny 25°F

Surface Owner: FEE

Other(Specify):

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

During tank removal activities at the Vonderlage 22, 13, 39, 40-36 O SA Facility, impacted soil was discovered adjacent to two of the above ground storage tanks (AST02 and AST03). The volume of the release is unknown. Assessment activities are ongoing. The assessment details will be summarized in a supplemental Form 27 report (Remediation No. 20744; Form 27 Initial Document No. 402867729). The topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

Date	Agency/Party	Contact	Phone	Response
12/14/2021	Weld County	Weld County	-	Notified via email
12/15/2021	Surface Owner	Surface Owner	-	Notified via voicemail

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

- No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.
- Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_
- Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_
- Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_
- No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.
- No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.
- No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak
- Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)
- Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_
- Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_
- Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_
- Was there damage during excavation? \_\_\_\_\_
- Was CO 811 notified prior to excavation? \_\_\_\_\_
- No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.
- Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_
- No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:
- ☐ The presence of free product or hydrocarbon sheen Surface Water
- ☐ The presence of free product or hydrocarbon sheen on Groundwater
- ☐ The presence of contaminated soil in contact with Groundwater
- ☐ The presence of contaminated soil in contact with Surface water

Yes	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

## SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 12/17/2021		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL			<input checked="" type="checkbox"/>
CONDENSATE			<input checked="" type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>YES</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, <b>including walls &amp; floor regardless of construction material</b>, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): _____		Width of Impact (feet): _____	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
Assessment and remediation activities are ongoing. Confirmation soil samples will be collected from the excavation area for laboratory analysis, as indicated in the Form 27 Initial (Remediation No. 20744; Form 27 Initial Document No. 402867729). The analytical results and assessment details will be provided in a supplemental Form 27 report. A Photo Log is included as an attachment.			
Soil/Geology Description:			
Clayey sand (SC)			
Depth to Groundwater (feet BGS) <u>20</u>		Number Water Wells within 1/2 mile radius: <u>13</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>240</u> None <input type="checkbox"/>	Surface Water <u>650</u> None <input type="checkbox"/>	
	Wetlands <u>4280</u> None <input type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>	
	Livestock <u>1580</u> None <input type="checkbox"/>	Occupied Building <u>1580</u> None <input type="checkbox"/>	
Additional Spill Details Not Provided Above:			

## CORRECTIVE ACTIONS

#1 Supplemental Report Date: 12/17/2021

Root Cause of Spill/Release Unknown (Historical)

Other (specify) \_\_\_\_\_

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

Above ground storage tank

Describe Incident & Root Cause (include specific equipment and point of failure)

During tank removal activities at the Vonderlage 22, 13, 39, 40-36 O SA Facility, impacted soil was discovered adjacent to two of the above ground storage tanks (AST02 and AST03). The volume of the release is unknown. Assessment activities are ongoing.

Describe measures taken to prevent the problem(s) from reoccurring:

The ASTs are being permanently removed and not replaced.

Volume of Soil Excavated (cubic yards): \_\_\_\_\_

Disposition of Excavated Soil (attach documentation) ☐ Offsite Disposal ☐ Onsite Treatment ☐ Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): \_\_\_\_\_

Volume of Impacted Surface Water Removed (bbls): \_\_\_\_\_

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

- Basis for Closure:
- ☐ Corrective Actions Completed (documentation attached, check all that apply)
    - ☐ Horizontal and Vertical extents of impacts have been delineated.
    - ☐ Documentation of compliance with Table 915-1 is attached.
    - ☐ All E&P Waste has been properly treated or disposed.
  - ☒ Work proceeding under an approved Form 27 (Rule 912.c).
 

Form 27 Remediation Project No: 20744
  - ☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

## OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Gregory Hamilton

Title: Environmental Consultant Date: 12/17/2021 Email: Gregory\_Hamilton@oxy.com

## Condition of Approval

**COA Type****Description**

	Based on review of the information to be submitted in project 20744 which is ongoing at this time, it is concluded that the proposed investigation activities and proposed remedial actions in the approved site investigation and remediation plan will be adequate to remediate impacted soils and groundwater at the site of the spill. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, further site investigation and/or remediation activities may be required at the site.
1 COA	

## Attachment List

**Att Doc Num****Name**

402898220	SPILL/RELEASE REPORT(I/S)
402899436	TOPOGRAPHIC MAP
402899437	CORRESPONDENCE
402899779	PHOTO DOCUMENTATION
402903813	FORM 19 SUBMITTED

Total Attach: 5 Files

## General Comments

**User Group****Comment****Comment Date**

Environmental	spill coordinates provided are on location 480210. changed location number to 480210 from well location as battery is not on well location	12/19/2021
---------------	--	------------

Total: 1 comment(s)