

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL /30-12 (PL30)

Location ID: 414077



Photo #5406 from entrance to location.



Photo #5407 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL /30-12 (PL30)

Location ID: 414077



Photo #5408 from entrance to location.



Photo #5409 Storage tank not labeled.

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL /30-12 (PL30)

Location ID: 414077



Photo #5410 Sight glass indicates the storage tank is full of an unknown fluid.



Photo #5411 Storage tanks starts at the weld.

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL /30-12 (PL30)

Location ID: 414077



Photo #5412 No battery sign located at the tank battery.

