

## Inspection Photos

Location Name: 29-4N-64W NWNE Johnson RC TB

Facility ID: 481073



**Photo #1 Tank Battery**

# Inspection Photos

Location Name: 29-4N-64W NWNE Johnson RC TB

Facility ID: 481073



**Photo #2 Removed Stained Soil**

**Photo #3 Marked Risers**