

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	barbless wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	barbless wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Ag Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		

Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 5		
Comment:	automation		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	sticker on meter box indicates current calibration		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.140750,-104.893130
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)	55 bbl	

Other (Type) _____				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:		shares containment with crude tank		
Corrective Action:				Date:
Wells Served By Facilities Above				
API Number		AirsID		
123-27009				
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 297184 Type: WELL API Number: 123-27009 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 12/20/2021 at approximately 1250 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: Oxy/Kerr McGee</p> <p align="center">Location: Paradize V16-22D</p> <p align="right">API # 05-123-27009</p> <p align="center">County: Weld</p> <p>While there, I observed a Wellsite and tank battery, SI at the time of inspection. During this inspection no compliance issues were observed: See attached photos. Location: dry, Weather: clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	12/20/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304677	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5612996