

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT ET AL-66S96W /35SESE

Location ID: 334743



Photo #5438 from entrance to location.



Photo #5439 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT ET AL-66S96W /35SESE

Location ID: 334743



Photo #5440 Multiple wellhead signs weathered and not legible.



Photo #5441 Storage tanks not labeled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT ET AL-66S96W /35SESE

Location ID: 334743



Photo #5442 Sight glass indicates the storage tank is full of an unknown fluid.



Photo #5443 Storage tank located under the horizontal separator.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT ET AL-66S96W /35SESE

Location ID: 334743




Photo #5444 Unused equipment.



Photo #5445 Debris inside tank containment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT ET AL-66S96W /35SESE

Location ID: 334743



Photo #5445 bird protectors missing.



Photo #5446 Vent pipe open ended and venting. No PRV or bull plug on vent pipe.