

Inspection Photos  
Operator: Simcoe  
API: 067-08500  
Date: 12/17/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with western wheatgrass, smooth brome, and sand dropseed.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with gambel oak, mountain mahogany, sagebrush, Indian ricegrass, blue grama, James galleta, and penstemon.