

Inspection Photos
Operator: Simcoe
API: 067-08412
Date: 12/17/2021



Photo 1. View of the project area from the well pad entrance facing center.

Russian olives



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing western wheatgrass. Approximately 5 Russian olives observed in the southern project area, need to be removed.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area comprised grass field developed for school field.