

Inspection Photos  
Operator: Simcoe  
API: 067-07558  
Date: 12/17/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with smooth brome, crested wheatgrass, and western wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area comprised of developed school infrastructure.