

Inspection Photos

API: 071-08810

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/21/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08810 | Date: 12/21/2021

Inspection Photos



Photo 1. Facing north along the access road. The access road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 12/21/2021

Inspection Photos



Photo 2. The area of erosion along the switch back of the road has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 12/21/2021

Inspection Photos



Photo 3. Facing northwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 12/21/2021

Inspection Photos



Photo 4. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 12/21/2021

Inspection Photos



Photo 5. Facing southwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 12/21/2021

Inspection Photos



Photo 6. East side of the location facing southwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 12/21/2021