

Inspection Photos

API: 071-09177

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/21/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09177 | Date: 12/21/2021

Inspection Photos



Photo 1. Drone aerial photo facing northwest toward the recontoured access road and location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09177 | Date: 12/21/2021

Inspection Photos



Photo 2. Drone aerial photo facing northwest toward the location. There are areas where erosion is occurring shown at red arrow. The vegetation is not establishing in areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09177 | Date: 12/21/2021

Inspection Photos



Photo 3. Facing down toward the recontoured location. There are areas of rilling erosion and the berms are not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09177 | Date: 12/21/2021

Inspection Photos



Photo 4. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09177 | Date: 12/21/2021

Inspection Photos



Photo 5. Facing east toward the adjacent flowline reclamation which has established native vegetation for comparison.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09177 | Date: 12/21/2021